

Technical Bulletin CS-11-05

8400 Reduced Battery Life



Problem

8440/8450 Phone has less than 25% the standby battery life expected

System Affected

Spectralink 8440 and Spectralink 8450

Description

Battery life can be impacted by many factors in a customer environment. You may notice a problem with battery in some phones running version 4.0.0.15769. The problem will be evident where phones experience less than 25% the expected standby battery life. On a full charge the phone will discharge the standard battery in less than 18 hours in a standby state. An extended life battery will discharge in less than 25 hours in a standby state.

Resolution

All 8400 Series handsets must be updated to version 4.0.0.20561

The information provided in the Polycom technical bulletin is provided "as is" without warranty of any kind. No obligation or liability will arise out of Polycom rendering technical or other advice or service in connection herewith.

Polycom® and the Polycom logo design are registered trademarks of Polycom, Inc. in the U.S. and various countries. All other trademarks are the property of their respective companies.

Effective Date: 6/30/2011